

Errata DIMM-Base Lothron-2

Rev	Date/Signature	Changes
1	6.10.2011/Sr	First Revision

1 Product affected

Product affected	Rev.
DIMM-EcoBase Verno	R2B

2 Errata 1 – Power over Ethernet

2.1 Description

The Power over Ethernet (PoE) function is disabled, because of an issue by switching between PoE and the 5V power supply input.

2.2 Projected Impact

The Power over Ethernet (PoE) function is not available at boards with hardware revision R2B.

2.3 Workaround

Ask emtrion for a modification of the baseboard to enable the PoE function and disable the 5V input for wall adapters. An automatic switching between PoE and 5V input is with the hardware revision R2B not possible.

2.4 Proposed Solution

This issue will be fixed at DIMM-Base Lothron R3A boards.